


Join diagram GM41A with diagram GM45B at line A - B

Delphi
Item #
80691

Diagram
GM41A
1 of 2
parts of
diagram
for
Stand-Up
GM 41



3380 E. Jolly Rd.
Lansing, MI 48910
www.DelphiGlass.com

Be Creative! 800.248.2048

Delphi Item # 80691

Join diagram GM41A with diagram GM41B at line A - B

Create glass figure to fit inside this diagram with legs in indicated areas. Fuse glass figure first, according to your own artistic preferences. Apply glass separator to Stand-Up mold according to the manufacturer's instructions. Place fused figure on mold in kiln and slump/drape at 350 degrees/hour to 1175 and hold for 10 minutes.

Diagram GM41B 1 of 2 parts of diagram for
Large Stand-Up GM 41



8.25"

7"



3380 E. Jolly Rd.
Lansing, MI 48910
www.DelphiGlass.com

Be Creative! 800.248.2048

B

A