

Tips for Using Crinklized Dichroic™

Crinklized Dichroic™ is MADE to be left exposed. The intrinsic nature of this new coating is much more exaggerated when the coating is allowed to push upwards and crinkle, crystallize and curl.

- Many of the Crinklized sheets appear to have an unusual reflective color prior to hotworking, especially when the coating is viewed from the back side of a clear sheet. This all fires away to reveal the same brilliant CBS Dichroic colors that everyone expects.
- Expect similar predictable color shifts when hotworking the new Crinklized Dichroic™ as with CBS original coatings.
- “Fire it hot”- For maximum effect, fuse the Crinklized Dichroic™ Coating to a peak temperature around 1475 degrees or higher. (Not applicable to lampworkers and furnace workers).